



City of **HOBART**

**MEMORANDUM: LORD MAYOR
DEPUTY LORD MAYOR
ELECTED MEMBERS**

RAILWAY ROUNDABOUT FOUNTAIN

Meeting: City Infrastructure Committee

Meeting date: 4 May 2022

Raised by: Lord Mayor Reynolds

Question: Can the Director provide an update on the Railway Roundabout Fountain and if it is currently undergoing repairs?

Response:

Repairs are currently being undertaken on the pumping system and lights.

The Pump recently failed and due to its age spare parts can no longer be obtained. A new pump is being sourced and we are awaiting costings and arrival dates of a new pump from the preferred contractor.

The current lighting system is starting to fail due to water ingress. A trial of three brands of different fittings will be undertaken over the next 3-6 months to determine the most suitable fitting for the location. A complete replacement of the current system is proposed in the 2023 – 2024 financial year.

As signatory to this report, I certify that, pursuant to Section 55(1) of the Local Government Act 1993, I hold no interest, as referred to in Section 49 of the Local Government Act 1993, in matters contained in this report.

Neil Noye
DIRECTOR CITY LIFE

Date: 20 May 2022
File Reference: F22/42503; 13-1-10